









|                 |                     |                    |                      |                     |                  |
|-----------------|---------------------|--------------------|----------------------|---------------------|------------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>         | <b>Time</b>      |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019          | 10:54 AM         |
| <b>Surveyor</b> | <b>Street</b>       |                    | <b>City</b>          | <b>Weather</b>      |                  |
| NICK            | ILLINOIS            |                    | GENEVA               | Dry                 |                  |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b>       |                  |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |                     |                  |
| <b>Comments</b> |                     |                    |                      | <b>Pre-Cleaning</b> | <b>TV Length</b> |
|                 |                     |                    |                      | Jetting             | 303              |

|   | Ftg.  | Code | Description | Position | Severity | Comment                   |
|---|-------|------|-------------|----------|----------|---------------------------|
|     | 0.0   | MH   | Manhole     | 12       |          |                           |
|   | 0.4   | C    | Crack       | 9        | 2        | FRACTURE                  |
|     | 67.7  | L    | Lateral     | 2        |          |                           |
|   | 71.9  | L    | Lateral     | 1        |          | STUB                      |
|   | 73.5  | L    | Lateral     | 10       |          | STUB                      |
|   | 120.8 | L    | Lateral     | 11       |          |                           |
|   | 122.5 | L    | Lateral     | 11       |          |                           |
|   | 168.1 | L    | Lateral     | 2        |          |                           |
|   | 168.9 | R    | Roots       | 9 to 11  | 3        | LIGHT ROOTS IN JOINT      |
|   | 170.1 | L    | Lateral     | 11       |          |                           |
|   | 221.8 | L    | Lateral     | 2        |          | LATERAL WITH LIGHT ROOTS  |
|   | 223.7 | L    | Lateral     | 10       |          |                           |
|   | 271.4 | L    | Lateral     | 2        |          | LATERAL WITH LIGHT ROOTS. |
|   | 273.3 | L    | Lateral     | 11       |          |                           |
|  | 303.0 | MH   | Manhole     | 12       |          |                           |


|                 |                     |                    |                      |                     |                  |
|-----------------|---------------------|--------------------|----------------------|---------------------|------------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>         | <b>Time</b>      |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019          | 10:54 AM         |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        |                      | <b>Weather</b>      |                  |
| NICK            | ILLINOIS            | GENEVA             |                      | Dry                 |                  |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b>       |                  |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |                     |                  |
| <b>Comments</b> |                     |                    |                      | <b>Pre-Cleaning</b> | <b>TV Length</b> |
|                 |                     |                    |                      | Jetting             | 303              |



MH - Manhole @ 0.0 ft.



C - Crack @ 0.4 ft. FRACTURE



L - Lateral @ 67.7 ft.




L - Lateral @ 71.9 ft. STUB


|                 |                     |                    |                      |                     |                  |
|-----------------|---------------------|--------------------|----------------------|---------------------|------------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>         | <b>Time</b>      |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019          | 10:54 AM         |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        |                      | <b>Weather</b>      |                  |
| NICK            | ILLINOIS            | GENEVA             |                      | Dry                 |                  |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b>       |                  |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |                     |                  |
| <b>Comments</b> |                     |                    |                      | <b>Pre-Cleaning</b> | <b>TV Length</b> |
|                 |                     |                    |                      | Jetting             | 303              |




L - Lateral @ 73.5 ft. STUB



L - Lateral @ 120.8 ft.




L - Lateral @ 122.5 ft.



L - Lateral @ 168.1 ft.

|                 |                     |                    |                      |                     |                  |
|-----------------|---------------------|--------------------|----------------------|---------------------|------------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>         | <b>Time</b>      |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019          | 10:54 AM         |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        |                      | <b>Weather</b>      |                  |
| NICK            | ILLINOIS            | GENEVA             |                      | Dry                 |                  |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b>       |                  |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |                     |                  |
| <b>Comments</b> |                     |                    |                      | <b>Pre-Cleaning</b> | <b>TV Length</b> |
|                 |                     |                    |                      | Jetting             | 303              |



R - Roots @ 168.9 ft. LIGHT ROOTS IN JOINT



L - Lateral @ 170.1 ft.




L - Lateral @ 221.8 ft. LATERAL WITH LIGHT ROOTS



L - Lateral @ 223.7 ft.

|                 |                     |                    |                      |                     |                  |
|-----------------|---------------------|--------------------|----------------------|---------------------|------------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>         | <b>Time</b>      |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019          | 10:54 AM         |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        |                      | <b>Weather</b>      |                  |
| NICK            | ILLINOIS            | GENEVA             |                      | Dry                 |                  |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b>       |                  |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |                     |                  |
| <b>Comments</b> |                     |                    |                      | <b>Pre-Cleaning</b> | <b>TV Length</b> |
|                 |                     |                    |                      | Jetting             | 303              |



L - Lateral @ 271.4 ft. LATERAL WITH LIGHT ROOTS.



L - Lateral @ 273.3 ft.




MH - Manhole @ 303.0 ft.

|                 |                     |                    |                      |               |             |
|-----------------|---------------------|--------------------|----------------------|---------------|-------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>   | <b>Time</b> |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019    | 10:54 AM    |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        | <b>Weather</b>       |               |             |
| NICK            | ILLINOIS            | GENEVA             | Dry                  |               |             |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b> |             |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |               |             |
| <b>Comments</b> | <b>Pre-Cleaning</b> | <b>TV Length</b>   |                      |               |             |
|                 | Jetting             | 303                |                      |               |             |

| Ftg.  | Code | Description | Position | Severity | Comment                   |
|-------|------|-------------|----------|----------|---------------------------|
| 0.0   | MH   | Manhole     | 12       |          |                           |
| 0.4   | C    | Crack       | 9        | 2        | FRACTURE                  |
| 67.7  | L    | Lateral     | 2        |          |                           |
| 71.9  | L    | Lateral     | 1        |          | STUB                      |
| 73.5  | L    | Lateral     | 10       |          | STUB                      |
| 120.8 | L    | Lateral     | 11       |          |                           |
| 122.5 | L    | Lateral     | 11       |          |                           |
| 168.1 | L    | Lateral     | 2        |          |                           |
| 168.9 | R    | Roots       | 9 to 11  | 3        | LIGHT ROOTS IN JOINT      |
| 170.1 | L    | Lateral     | 11       |          |                           |
| 221.8 | L    | Lateral     | 2        |          | LATERAL WITH LIGHT ROOTS  |
| 223.7 | L    | Lateral     | 10       |          |                           |
| 271.4 | L    | Lateral     | 2        |          | LATERAL WITH LIGHT ROOTS. |
| 273.3 | L    | Lateral     | 11       |          |                           |
| 303.0 | MH   | Manhole     | 12       |          |                           |

|                         |  |                              |                                      |                                |                         |
|-------------------------|--|------------------------------|--------------------------------------|--------------------------------|-------------------------|
| <b>Owner</b>            | <b>Customer</b>                        | <b>Upstream MH</b><br>1RM11  | <b>Downstream MH</b><br>1RM18        | <b>Date</b><br>03-13-2019      | <b>Time</b><br>10:54 AM |
| <b>Surveyor</b><br>NICK | <b>Street</b><br>ILLINOIS              |                              | <b>City</b><br>GENEVA                | <b>Weather</b><br>Dry          |                         |
| <b>Size</b><br>8        | <b>Material</b><br>Vitrified Clay Pipe | <b>Sewer Use</b><br>Sanitary | <b>Purpose</b><br>Routine Assessment |                                | <b>Length</b>           |
| <b>Comments</b>         |  |                              |                                      | <b>Pre-Cleaning</b><br>Jetting | <b>TV Length</b><br>303 |



|                 |                     |                    |                      |               |             |
|-----------------|---------------------|--------------------|----------------------|---------------|-------------|
| <b>Owner</b>    | <b>Customer</b>     | <b>Upstream MH</b> | <b>Downstream MH</b> | <b>Date</b>   | <b>Time</b> |
|                 |                     | 1RM11              | 1RM18                | 03-13-2019    | 10:54 AM    |
| <b>Surveyor</b> | <b>Street</b>       | <b>City</b>        | <b>Weather</b>       |               |             |
| NICK            | ILLINOIS            | GENEVA             | Dry                  |               |             |
| <b>Size</b>     | <b>Material</b>     | <b>Sewer Use</b>   | <b>Purpose</b>       | <b>Length</b> |             |
| 8               | Vitrified Clay Pipe | Sanitary           | Routine Assessment   |               |             |
| <b>Comments</b> | <b>Pre-Cleaning</b> | <b>TV Length</b>   |                      |               |             |
|                 | Jetting             | 303                |                      |               |             |

**Distance (ft)**

