

Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 001

Video 00:00:53
Distance 8.40 m

PVC to clay



Picture 002

Video 00:01:21
Distance 12.90 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 003

Video 00:03:20
Distance 47.50 m

Abandoned service at 1



Picture 004

Video 00:04:29
Distance 49.40 m

Lateral at 12



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 005

Video 00:04:45
Distance 50.40 m

Service at 12



Picture 006

Video 00:05:42
Distance 68.00 m

Hole



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 007

Video 00:06:16
Distance 77.50 m

CRACK



Picture 008

Video 00:06:37
Distance 79.50 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 009

Video 00:06:56
Distance 81.50 m

CRACK



Picture 010

Video 00:07:27
Distance 87.60 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 011

Video 00:07:51
Distance 91.80 m

HOLE



Picture 012

Video 00:08:13
Distance 96.00 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 013

Video 00:08:33
Distance 98.00 m


CRACK



Picture 014

Video 00:09:09
Distance 105.10 m

Service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 015

Video 00:09:48
Distance 107.10 m

Abandoned service at 11



Picture 016

Video 00:10:04
Distance 107.90 m

HOLE



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 017

Video 00:11:25
Distance 132.60 m

Roots joint



Picture 018

Video 00:12:01
Distance 134.20 m

Roots joint medium



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 019

Video 00:15:30
Distance 134.80 m

Service at 11



Picture 020

Video 00:15:49
Distance 134.80 m

Roots growing from lateral large



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 021

Video 00:16:14
Distance 138.60 m

Roots joint fine



Picture 022

Video 00:16:37
Distance 141.40 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 023

Video 00:16:58
Distance 144.90 m

Roots joint fine



Picture 024

Video 00:17:18
Distance 146.00 m

Service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 025

Video 00:17:37
Distance 146.00 m

Roots lateral large



Picture 026

Video 00:18:06
Distance 148.30 m

Abandoned service at 11



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 027

Video 00:18:22
Distance 149.10 m

Roots joint fine



Picture 028

Video 00:18:32
Distance 151.00 m

Roots joint fine



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 029

Video 00:18:49
Distance 153.10 m

Roots joint medium



Picture 030

Video 00:19:14
Distance 158.00 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 031

Video 00:19:46
Distance 169.90 m

CRACK



Picture 032

Video 00:20:26
Distance 171.90 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 033

Video 00:20:39
Distance 174.00 m


CRACK



Picture 034

Video 00:20:47
Distance 176.30 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 035

Video 00:20:56
Distance 178.20 m

CRACK



Picture 036

Video 00:21:06
Distance 180.20 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 037

Video 00:21:13
Distance 182.30 m

CRACK



Picture 038

Video 00:21:20
Distance 184.40 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 039
Video 00:21:28
Distance 186.20 m
HOLE, Hole, Crack



Picture 040
Video 00:21:37
Distance 188.40 m
CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 041

Video 00:21:54
Distance 194.60 m

CRACK



Picture 042

Video 00:22:03
Distance 197.00 m

CRACK



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 043

Video 00:22:11
Distance 198.70 m

CRACK



Picture 044

Video 00:22:35
Distance 202.10 m

Service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 045

Video 00:23:14
Distance 203.20 m

Crack



Picture 046

Video 00:23:27
Distance 204.00 m

Service at 11



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 047
Video 00:23:40
Distance 205.10 m
Crack



Picture 048
Video 00:23:54
Distance 208.90 m
Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 049

Video 00:24:05
Distance 211.50 m

Crack



Picture 050

Video 00:24:15
Distance 213.40 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 051

Video 00:24:36
Distance 219.70 m

Crack



Picture 052

Video 00:24:43
Distance 221.80 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 053

Video 00:24:53
Distance 225.70 m

Crack



Picture 054

Video 00:25:03
Distance 230.00 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 055

Video 00:25:20
Distance 231.70 m

Roots joint fine



Picture 056

Video 00:25:31
Distance 233.80 m

Roots joint fine



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 057

Video 00:25:37
Distance 235.80 m

Roots joint fine



Picture 058

Video 00:25:48
Distance 238.30 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 059

Video 00:25:56
Distance 240.00 m

Roots joint fine



Picture 060

Video 00:26:14
Distance 246.70 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 061

Video 00:26:22
Distance 248.40 m

Roots joint fine



Picture 062

Video 00:27:11
Distance 249.20 m

Lateral, Service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 063

Video 00:27:28
Distance 249.20 m

ROOTS IN LATERAL large



Picture 064

Video 00:29:32
Distance 251.20 m

Service at 11




Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 065

Video 00:29:55
Distance 251.20 m

Roots growing from lateral large



Picture 066

Video 00:30:19
Distance 254.70 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 067

Video 00:30:35
Distance 257.20 m

Crack



Picture 068

Video 00:31:00
Distance 267.30 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 069

Video 00:31:18
Distance 269.20 m

Crack



Picture 070

Video 00:31:27
Distance 271.20 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 071

Video 00:31:34
Distance 273.30 m

Crack



Picture 072

Video 00:33:40
Distance 301.40 m

Service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 073

Video 00:34:00
Distance 303.30 m

Service at 11



Picture 074

Video 00:34:21
Distance 304.30 m

HOLE, Hole, Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 075

Video 00:36:54
Distance 348.30 m

Service at 11



Picture 076

Video 00:37:27
Distance 350.50 m

Abandoned service at 1



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 077

Video 00:37:43
Distance 352.40 m

Abandoned service at 11



Picture 078

Video 00:39:29
Distance 376.30 m

Crack



Protocol of recordings

Date 24/02/2022
Recording 1RM25- 1RM37 Illinois 8 in clay downstream 2-24-2022

Picture 081

Video 00:41:17
Distance 390.10 m

Manhole

