






<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	ILLINOIS		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2

	Ftg.	Code	Description	Position	Severity	Comment
 	0.1	MH	Manhole	12		
	3.3	L	Lateral	12		STUB
	5.6	L	Lateral	11		
	26.8	R	Roots	9 to 10	3	
	46.7	L	Lateral	3		
	60.7	L	Lateral	2		
	62.8	L	Lateral	11		
	117.2	L	Lateral	12		
	119.8	R	Roots	11 to 2	3	
 	173.1	L	Lateral	11		
	174.5	L	Lateral	2		
	216.6	R	Roots	3 to 4	3	
	219.8	L	Lateral	2		
	222.8	L	Lateral	12		
	260.2	MH	Manhole	12		


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	ILLINOIS		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>		<b>Length</b>
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2




MH - Manhole @ 0.1 ft.



L - Lateral @ 3.3 ft. STUB




L - Lateral @ 5.6 ft.




R - Roots @ 26.8 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	ILLINOIS	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2



L - Lateral @ 46.7 ft.



L - Lateral @ 60.7 ft.




L - Lateral @ 62.8 ft.



L - Lateral @ 117.2 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	ILLINOIS		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2




R - Roots @ 119.8 ft.



L - Lateral @ 173.1 ft.



L - Lateral @ 174.5 ft.




R - Roots @ 216.6 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	ILLINOIS	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2



L - Lateral @ 219.8 ft.



L - Lateral @ 222.8 ft.




MH - Manhole @ 260.2 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	ILLINOIS		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2

Ftg.	Code	Description	Position	Severity	Comment
0.1	MH	Manhole	12		
3.3	L	Lateral	12		STUB
5.6	L	Lateral	11		
26.8	R	Roots	9 to 10	3	
46.7	L	Lateral	3		
60.7	L	Lateral	2		
62.8	L	Lateral	11		
117.2	L	Lateral	12		
119.8	R	Roots	11 to 2	3	
173.1	L	Lateral	11		
174.5	L	Lateral	2		
216.6	R	Roots	3 to 4	3	
219.8	L	Lateral	2		
222.8	L	Lateral	12		
260.2	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	ILLINOIS	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2RM04	1RM36	08-16-2019	10:39 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	ILLINOIS		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	260.2

Distance (ft)

