

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	2ND		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3

	Ftg.	Code	Description	Position	Severity	Comment
	0.0	MH	Manhole	12		
	0.6	R	Roots	8 to 4	3	
	3.5	L	Lateral	2		STUB
	5.7	L	Lateral	3		LATERAL WITH ROOTS
	32.1	L	Lateral	10		STUB
	44.3	L	Lateral	3		
	76.8	L	Lateral	10		STUB
	78.9	L	Lateral	3		
	85.7	R	Roots	7 to 9	3	LIGHT ROOTS
	119.4	L	Lateral	10		STUB
121.5	L	Lateral	3			
174.3	L	Lateral	10		STUB	
176.3	L	Lateral	2		STUB	
235.3	MH	Manhole	12			


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	2ND	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
AFTER ROOT CUTTING.	Jetting	235.3			




MH - Manhole @ 0.0 ft.



R - Roots @ 0.6 ft.




L - Lateral @ 3.5 ft. STUB




L - Lateral @ 5.7 ft. LATERAL WITH ROOTS

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	2ND	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3




L - Lateral @ 32.1 ft. STUB



L - Lateral @ 44.3 ft.



L - Lateral @ 76.8 ft. STUB



L - Lateral @ 78.9 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	2ND	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3



R - Roots @ 85.7 ft. LIGHT ROOTS



L - Lateral @ 119.4 ft. STUB




L - Lateral @ 121.5 ft.




L - Lateral @ 174.3 ft. STUB

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	2ND		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3



L - Lateral @ 176.3 ft. STUB




MH - Manhole @ 235.3 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	2ND		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole	12		
0.6	R	Roots	8 to 4	3	
3.5	L	Lateral	2		STUB
5.7	L	Lateral	3		LATERAL WITH ROOTS
32.1	L	Lateral	10		STUB
44.3	L	Lateral	3		
76.8	L	Lateral	10		STUB
78.9	L	Lateral	3		
85.7	R	Roots	7 to 9	3	LIGHT ROOTS
119.4	L	Lateral	10		STUB
121.5	L	Lateral	3		
174.3	L	Lateral	10		STUB
176.3	L	Lateral	2		STUB
235.3	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b> 2SM17	<b>Downstream MH</b> 2SM21	<b>Date</b> 12-27-2019	<b>Time</b> 9:49 AM
<b>Surveyor</b> NICK	<b>Street</b> 2ND		<b>City</b> GENEVA	<b>Weather</b> Dry	
<b>Size</b> 6	<b>Material</b> Vitrified Clay Pipe	<b>Sewer Use</b> Sanitary	<b>Purpose</b> Routine Assessment		<b>Length</b>
<b>Comments</b> AFTER ROOT CUTTING.				<b>Pre-Cleaning</b> Jetting	<b>TV Length</b> 235.3



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		2SM17	2SM21	12-27-2019	9:49 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	2ND		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
AFTER ROOT CUTTING.				Jetting	235.3

Distance (ft)

