



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	SIMPSON		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	13.8




<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	SIMPSON	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	13.8			



MH - Manhole @ 0.0 ft.



G - Grease @ 4.7 ft.




H - Hole @ 10.4 ft.



JO - Joint Offset @ 10.4 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	SIMPSON	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	13.8



R - Roots @ 10.7 ft.



R - Roots @ 13.5 ft.




MH - Manhole @ 13.8 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	SIMPSON	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	13.8			

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole	12		
4.7	G	Grease	11 to 3	2	
10.4	H	Hole		4	
10.4	JO	Joint Offset		2	
10.7	R	Roots	2 to 4	3	
13.5	R	Roots		3	
13.8	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	SIMPSON	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	13.8



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		3VM37	3VM38	01-13-2021	9:42 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	SIMPSON	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	13.8			

**Distance (ft)**

