






















<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	256.6

	Ftg.	Code	Description	Position	Severity	Comment
	0.0	MH	Manhole	12		START MH 4UM09
	7.9	C	Crack	7 to 12	2	
	10.9	C	Crack	8 to 11	2	
	19.2	C	Crack	1 to 4	2	
	25.6	L	Lateral	10		
	29.0	L	Lateral	3		
	32.7	C	Crack	11 to 1	2	
	39.3	L	Lateral	9		
	40.8	L	Lateral	2		
	75.3	L	Lateral			ROOTS AROUND LATERAL OUTSIDE OFFSET IN LATERAL WITH ROOTS
	76.8	L	Lateral	2		
	100.9	C	Crack	10 to 10	2	
	114.0	L	Lateral	11		
	127.8	C	Crack	11 to 2	2	
						
	158.0	L	Lateral	12		
	159.2	L	Lateral	12		
	186.2	L	Lateral	2		
	209.4	L	Lateral	12		
	256.6	MH	Manhole	12		END MH 4UM02


Owner	Customer	Upstream MH	Downstream MH	Date	Time
		4UM09	4UM02	06-14-2021	12:50 PM
Surveyor	Street	City	Weather		
JEREMY	NEBRASKA	GENEVA	Dry		
Size	Material	Sewer Use	Purpose	Length	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
Comments	Pre-Cleaning	TV Length			
	Jetting	256.6			




MH - Manhole @ 0.0 ft. START MH 4UM09



C - Crack @ 7.9 ft.




C - Crack @ 10.9 ft.



C - Crack @ 19.2 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	256.6



L - Lateral @ 25.6 ft.



L - Lateral @ 29.0 ft.




C - Crack @ 32.7 ft.



L - Lateral @ 39.3 ft.

Owner	Customer	Upstream MH	Downstream MH	Date	Time
		4UM09	4UM02	06-14-2021	12:50 PM
Surveyor	Street	City	Weather		
JEREMY	NEBRASKA	GENEVA	Dry		
Size	Material	Sewer Use	Purpose	Length	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
Comments	Pre-Cleaning	TV Length			
	Jetting	256.6			



L - Lateral @ 40.8 ft.



L - Lateral @ 75.3 ft. ROOTS AROUND LATERAL OUTSIDE




L - Lateral @ 76.8 ft. OFFSET IN LATERAL WITH ROOTS




C - Crack @ 100.9 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	256.6




L - Lateral @ 114.0 ft.



C - Crack @ 127.8 ft.




L - Lateral @ 158.0 ft.




L - Lateral @ 159.2 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	256.6



L - Lateral @ 186.2 ft.



L - Lateral @ 209.4 ft.




MH - Manhole @ 256.6 ft. END MH 4UM02

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	256.6			

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole	12		START MH 4UM09
7.9	C	Crack	7 to 12	2	
10.9	C	Crack	8 to 11	2	
19.2	C	Crack	1 to 4	2	
25.6	L	Lateral	10		
29.0	L	Lateral	3		
32.7	C	Crack	11 to 1	2	
39.3	L	Lateral	9		
40.8	L	Lateral	2		
75.3	L	Lateral			ROOTS AROUND LATERAL OUTSIDE
76.8	L	Lateral	2		OFFSET IN LATERAL WITH ROOTS
100.9	C	Crack	10 to 10	2	
114.0	L	Lateral	11		
127.8	C	Crack	11 to 2	2	
158.0	L	Lateral	12		
159.2	L	Lateral	12		
186.2	L	Lateral	2		
209.4	L	Lateral	12		
256.6	MH	Manhole	12		END MH 4UM02

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	256.6



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM09	4UM02	06-14-2021	12:50 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
JEREMY	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
6	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	256.6			

### Distance (ft)

