


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	NEBRASKA		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	136.4



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	NEBRASKA		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	136.4




MH - Manhole @ 0.0 ft.



L - Lateral @ 48.3 ft.




L - Lateral @ 50.9 ft.




DP - Deposits @ 53.4 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	136.4			




C - Crack @ 60.8 ft.



DP - Deposits @ 61.9 ft.




DP - Deposits @ 65.6 ft.



DP - Deposits @ 73.8 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	136.4			




DP - Deposits @ 92.7 ft.



L - Lateral @ 100.8 ft.



L - Lateral @ 118.9 ft.




MH - Manhole @ 136.4 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	136.4

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole	12		
48.3	L	Lateral	3		
50.9	L	Lateral	9		
53.4	DP	Deposits		2	
60.8	C	Crack	8 to 12	2	
61.9	DP	Deposits	1 to 5	2	
65.6	DP	Deposits		2	
73.8	DP	Deposits		2	
92.7	DP	Deposits		2	
100.8	L	Lateral	10		
118.9	L	Lateral	2		
136.4	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	NEBRASKA		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	136.4



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4UM14	4UM09	05-27-2021	1:49 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	NEBRASKA	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	136.4

Distance (ft)

