




<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	CAROLINE		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	CAROLINE	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1




MH - Manhole @ 0.0 ft.



L - Lateral @ 89.4 ft. SERVICE WITH HEAVY ROOTS.




L - Lateral @ 91.6 ft.



R - Roots @ 161.0 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	CAROLINE	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1




R - Roots @ 164.5 ft.



R - Roots @ 172.7 ft.




R - Roots @ 176.7 ft.



R - Roots @ 193.2 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	CAROLINE		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1



R - Roots @ 205.1 ft.




MH - Manhole @ 210.1 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	CAROLINE		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole	12		
89.4	L	Lateral	3		SERVICE WITH HEAVY ROOTS.
91.6	L	Lateral	9		
161.0	R	Roots		3	
164.5	R	Roots		3	
172.7	R	Roots		3	
176.7	R	Roots		3	
193.2	R	Roots		3	
205.1	R	Roots		3	
210.1	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>		<b>Weather</b>	
NICK	CAROLINE	GENEVA		Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	210.1



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM12	4VM14	01-13-2021	1:41 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	210.1			

Distance (ft)

