



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
NICK	CAROLINE		GENEVA	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	203

	Ftg.	Code	Description	Position	Severity	Comment
	0.1	MH	Manhole	12		
	2.8	R	Roots		3	
	12.8	R	Roots		3	
	24.2	R	Roots		3	
	25.9	R	Roots		3	
	35.3	L	Lateral	3		
	45.5	R	Roots		3	SERVICE WITH ROOTS PROTRUDING INTO MAIN
	48.2	L	Lateral	10		
	48.5	R	Roots		3	
	83.1	R	Roots		3	
	88.1	R	Roots		3	
	92.9	R	Roots		3	
	103.0	R	Roots		3	
	110.0	L	Lateral	3		SERVICE WITH ROOTS
	187.1	L	Lateral	3		
203.0	MH	Manhole	12			


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	203




MH - Manhole @ 0.1 ft.



R - Roots @ 2.8 ft.




R - Roots @ 12.8 ft.



R - Roots @ 24.2 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	203			




R - Roots @ 25.9 ft.



L - Lateral @ 35.3 ft.




R - Roots @ 45.5 ft.



L - Lateral @ 48.2 ft. SERVICE WITH ROOTS PROTRUDING INTO MAIN


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	203




R - Roots @ 48.5 ft.



R - Roots @ 83.1 ft.




R - Roots @ 88.1 ft.




R - Roots @ 92.9 ft.


<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	203



R - Roots @ 103.0 ft.



L - Lateral @ 110.0 ft. SERVICE WITH ROOTS



L - Lateral @ 187.1 ft.



MH - Manhole @ 203.0 ft.

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	203

Ftg.	Code	Description	Position	Severity	Comment
0.1	MH	Manhole	12		
2.8	R	Roots		3	
12.8	R	Roots		3	
24.2	R	Roots		3	
25.9	R	Roots		3	
35.3	L	Lateral	3		
45.5	R	Roots		3	
48.2	L	Lateral	10		SERVICE WITH ROOTS PROTRUDING INTO MAIN
48.5	R	Roots		3	
83.1	R	Roots		3	
88.1	R	Roots		3	
92.9	R	Roots		3	
103.0	R	Roots		3	
110.0	L	Lateral	3		SERVICE WITH ROOTS
187.1	L	Lateral	3		
203.0	MH	Manhole	12		

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b> 4VM14	<b>Downstream MH</b> 4VM20	<b>Date</b> 01-14-2021	<b>Time</b> 8:07 AM
<b>Surveyor</b> NICK	<b>Street</b> CAROLINE		<b>City</b> GENEVA	<b>Weather</b> Dry	
<b>Size</b> 8	<b>Material</b> Vitrified Clay Pipe	<b>Sewer Use</b> Sanitary	<b>Purpose</b> Routine Assessment		<b>Length</b>
<b>Comments</b>				<b>Pre-Cleaning</b> Jetting	<b>TV Length</b> 203



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4VM14	4VM20	01-14-2021	8:07 AM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
NICK	CAROLINE	GENEVA	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Vitrified Clay Pipe	Sanitary	Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	203			

**Distance (ft)**

