





<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		40M09	40M08	10-24-2016	1:04 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
john	South		Geneva	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>		<b>Length</b>
8	Clay Tile		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	42.6




R - Roots @ 23.9 ft. Light roots in joint previously cut

MH - Manhole @ 42.6 ft. End Manhole 40M08

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4OM09	4OM08	10-24-2016	1:04 PM
<b>Surveyor</b>	<b>Street</b>	<b>City</b>	<b>Weather</b>		
john	South	Geneva	Dry		
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Clay Tile		Routine Assessment		
<b>Comments</b>	<b>Pre-Cleaning</b>	<b>TV Length</b>			
	Jetting	42.6			

Ftg.	Code	Description	Position	Severity	Comment
23.9	R	Roots	11 to 3	3	Light roots in joint previously cut
42.6	MH	Manhole			End Manhole 4OM08

<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4OM09	4OM08	10-24-2016	1:04 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
john	South		Geneva	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Clay Tile		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	42.6



<b>Owner</b>	<b>Customer</b>	<b>Upstream MH</b>	<b>Downstream MH</b>	<b>Date</b>	<b>Time</b>
		4OM09	4OM08	10-24-2016	1:04 PM
<b>Surveyor</b>	<b>Street</b>		<b>City</b>	<b>Weather</b>	
john	South		Geneva	Dry	
<b>Size</b>	<b>Material</b>	<b>Sewer Use</b>	<b>Purpose</b>	<b>Length</b>	
8	Clay Tile		Routine Assessment		
<b>Comments</b>				<b>Pre-Cleaning</b>	<b>TV Length</b>
				Jetting	42.6

